

State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION PRIMARY RECORD		Primary	
		HRI #	
		Trinomial	
		NRHP Status Code	
Other			
Review Code		Reviewer	Date

Page 1 of 4

*Resource Name or #: (Assigned by Recorder) 4920 S. Soto Street

P1. Other Identifier: _____

*P2. Location: **Not for Publication** ☒ **Unrestricted** *a. County Los Angeles

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad South Gate Date 1978 T 2S ; R 13W ; 1/4 of 1/4 of Sec 1 ; S.B. B.M

c. Address 4920 S. Soto Street City Vernon Zip 90058

d. UTM: (Give more than one for large and/or linear resources) Zone: 11 ; 1 mE/ 1 mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc., as appropriate)

APN # 6303-023-009

*P3a. Description (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The structure is a commercial single story building composed of brick and reinforced concrete. The roof is flat and is covered in a tar/composite material. The main façade features two banks of 33 single pane windows, with two louvered windows on the Soto Street side. To the rear of the main structure is a corrugated metal garage/storage area. The roof is also composed of corrugated metal. The condition of both structures is good.

The setting is a mix of industrial and commercial. The building is located on the northeast corner of the intersection of S. Soto Street and E 50th Street. The structure is surrounded by other light industrial buildings and railroad spurs.

*P3b. Resource Attributes: (List attributes and codes) HP6 (1-3 story commercial building)

*P4. Resources present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)

See Continuation sheet for photos.

P5b. Description of Photo: (View, date, accession #)

See Continuation sheet for photos.

*P6. Date Constructed/Age and

Sources: ☒ Historic

☐ Prehistoric ☐ Both

1945-1969

*P7. Owner and Address:

Soto Tamarack
4920 S. Soto Street
Vernon, CA 90058

*P8. Recorded by: (Name, affiliation, and address)

Kelly Heidecker and Jeff Creighton
Parsons
2233 Watt Ave, Suite #330
Sacramento, CA 95825

*P9. Date Recorded:

June 30, 2002

*P10. Survey Type: (Describe)

Intensive

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Malburg Generating Station Project Cultural Resources Inventory Report

*Attachments: NONE ☒ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (List): _____

DPR 523A (1/95) *Required Information